

To: CN=Robert Goo/OU=DC/O=USEPA/C=US@EPA;CN=Joyce Hudson/OU=DC/O=USEPA/C=US@EPA;CN=Maureen Tooke/OU=DC/O=USEPA/C=US@EPA[]; N=Joyce Hudson/OU=DC/O=USEPA/C=US@EPA;CN=Maureen Tooke/OU=DC/O=USEPA/C=US@EPA[]; N=Maureen Tooke/OU=DC/O=USEPA/C=US@EPA[]
Cc: TROX.Randall@deq.state.or.us[]
Bcc: []
From: CN=Don Waye/OU=DC/O=USEPA/C=US
Sent: Wed 10/10/2012 6:30:43 PM
Subject: Time of Transfer OSDS Inspections?

Robert, Joyce & Maureen,

Oregon's Randy Trox is preparing to defend the state's proposed OSDS time-of-transfer inspections rule across its designated coastal nonpoint management area. Predictably, the effort is facing strong resistance from the real estate lobby. The legislature (or subcommittee?) wants to know where else this type of program has been put in place. He thinks that Delaware and North Carolina may have similar programs. Do you know? (We know about Iowa's program already.) If you have info or names/contact info for these state programs, will you please share them with Randy (cc me)?

Thanks.

Don Waye
U.S. Environmental Protection Agency
Nonpoint Source Control Branch (OWOW/AWPD)

USPS Mailing Address:	Office (FedEx/UPS delivery):
Mail Code 4503T	Room 7417H
1200 Pennsylvania Ave, NW	1301 Constitution Ave, NW
Washington, DC 20460	Washington, DC 20004

Phone: (202) 566-1170	Fax: (202) 566-1331
Email: waye.don@epa.gov	Website: epa.gov/nps